

Jan. 12
1952.

The Powers Regulator Company,
Chicago, Ill.

Dear Sirs;--

A few weeks ago, I purchased from a second hand dealer, one of your water mixers which had been in use at Los Alamos. On taking it apart, when it failed to work, my plumber has found that the thermostat is not working at all. Also it seems that some screws had been broken off in an attempt to open the casing. This is mixer No. S 26188 Size C20. Max temp. 115 deg.

Can you give me any idea of the cost to put this mixer in working order and what parts would be necessary to send in to you? The outside case is in good condition except the screws, and I presume that new internal parts can be had to put the whole in working shape.

Very truly yours,