

LAURA GILPIN



PHOTOGRAPHER

Box 1173 • Santa Fe, New Mexico

Sept. 5th
1967

Mr. Adolph Gasser,
5733 Geary Blvd.
San Francisco, Calif.

Dear Mr. Gasser:-

I was just writing to you when your note came. I was getting worried about my Medalist Camera. I sent a letter when the camera was mailed. I don't remember now whether I taped the letter onto the package or sent it separately. Anyway, here is what needs to be done.

1. There must be a bad connection in the flash wiring. I checked very carefully after it failed me, and found that it must be in the camera. ~~Second~~

2. There is a slight leak from the back (roll film back). There is a slight light streak along the edge of a roll, this does not occur in my second camera.

3. Check the plate back for adjustment and the little catch that is supposed to bring this back into focus.

4. Clean, and see that everything else is working.

I am also having some trouble with my other camera, so I need the one you have soon. I do hope that you can get at it at once. I shipped it from here July 20th.

Thanking you for prompt attention on this,

Very truly yours,