

Adolph Gasser, Inc.
3733 Geary Blvd.
San Francisco, Calif.

Oct.9,
1971

Dear Mr. Debye:-

I was very much dismayed to receive your letter of the 4th regarding my Medalist camera. I had had a letter from Mr. Gasser assuring me of its repair. Now after nearly two months I get this word from you.

I am writing to other repair places around the country in hopes that I can find some hope of worn parts. In the meantime if you will do the following to this camera of mine and return it as soon as possible.

1. Adjust plate back so I can use the camera for film pack and cut film holders.
2. See if cocking mechanism is working
3. Adjust depth of field scale.
4. See if cable release mechanism is working.

These will make it possible for me to use the camera.

The other camera must be a Medalist (I) the first one made for the Navy during World War II. The plastic bellows was the chief trouble maker with it.

The four items listed above should not take long and I trust that you can send the camera very soon. The worn part I am sure was the film advance stop when using roll film.

I shall hope to find some other repair place to fix my second camera.

Very truly yours,